

**To:** Daly, Eric[Daly.Eric@epa.gov]; 'Leonard Pimm'[bowlen300@aol.com]  
**Cc:** Pellegrino, Carl[Pellegrino.Carl@epa.gov]; 'Francisco Rodriguez'[frodriguez@gesoncall.com]; Lisichenko, Peter[lisichenko.peter@epa.gov]  
**From:** William Burg  
**Sent:** Thur 2/23/2017 9:00:19 PM  
**Subject:** RE: Please respond: NFB GNBC Office Area Rebuild

Tank is being replaced tomorrow morning

Bill Burg

GNBC

**From:** Daly, Eric [mailto:Daly.Eric@epa.gov]  
**Sent:** Thursday, February 23, 2017 10:30 AM  
**To:** Leonard Pimm; William Burg  
**Cc:** Pellegrino, Carl; Francisco Rodriguez; Lisichenko, Peter  
**Subject:** Please respond: NFB GNBC Office Area Rebuild  
**Importance:** High

Good Morning Len and Bill:

How are you both? We are moving along with the rebuild. Framing is nearly complete. We have plumbers, electricians, HVAC personnel in and out during the weeks as well as inspectors.

The plumber finished with his rough in and ran the water to check for leaks. It was discovered that the hot water heater in the GNBC main building is not working. That unit must be replaced and in working condition when the plumbing inspector comes for the final inspection. I was told there is about a two week window before the final inspection. This is obviously not part of our rebuild responsibility. Please let us know how this will be handled in order for the inspection process to be finalized smoothly.

I hope all is well.

Thanks

Regards,

Eric M. Daly  
On-Scene Coordinator/Radiological Response Specialist  
US Environmental Protection Agency- Region II

ERRD/RPB/PPS  
2890 Woodbridge Avenue  
Edison, NJ 08837  
[daly.eric@epa.gov](mailto:daly.eric@epa.gov)  
908-420-1707

"We must, indeed, all hang together, or assuredly we shall all hang separately", Benjamin Franklin